


Appln No. 10/562,171
Amdt. Dated August 6, 2008
Response to Office Action of February 6, 2008
Annotated Sheet # 1

**Typical fault current characteristics
at a substation LV side**



Appln No. 10/562,171
Amdt. Dated August 6, 2008
Response to Office Action of February 6, 2008
Annotated Sheet # 2

Transient fault current per transformer
SC-FCL Design option 2




Fig. 2

PRIOR ART

added →

Appln No. 10/562,171
Amdt. Dated August 6, 2008
Response to Office Action of February 6, 2008
Annotated Sheet # 4

